

# Temple 770

## DESCRIPTION AND GENERAL PROPERTIES

- **Material** PVC
- **Length (cm)** 30
- **Thickness (mm)**
- **Wrist** Straight cuff
- **Colour/Color** Blue
- **Interior finish** Jersey support, lined with woolen fleece
- **Exterior finish** Pebbled
- **Size / EAN** 9 10
- **Packaging** 1 pair/bag - 48 pairs/carton
- **Complementary information** Guaranteed without silicone



## PERFORMANCE RESULTS

Certification category 3

CE 0334



121



Type B



KMO



4221X

### Legends

#### ANSI CUT RESISTANCE

<b>A1</b>	<b>A1</b> ≥ 200 G	<b>A4</b> ≥ 1500 G	<b>A7</b> ≥ 4000 G
	<b>A2</b> ≥ 500 G	<b>A5</b> ≥ 2200 G	<b>A8</b> ≥ 5000 G
<b>CUT</b>	<b>A3</b> ≥ 1000 G	<b>A6</b> ≥ 3000 G	<b>A9</b> ≥ 6000 G

#### EN 511 COLD HAZARDS

PERFORMANCE LEVELS	0-4	0-4	0 or 1
Water permeability			
Contact cold resistance			
Convective cold resistance			

#### EN 407 THERMAL RISKS

Heat and fire

PERFORMANCE LEVELS	0-4	0-4	0-4	0-4	0-4	0-4
Resistance to large quantities of molten metal						
Resistance to small drops of molten metal						
Radiant heat resistant						
Convective heat resistance						
Contact heat resistance						
Burning behaviour						

### PROTECTION FROM PESTICIDES

ISO 18889	ISO 18889	ISO 18889
<b>G1</b>	<b>G2</b>	<b>GR</b>

### MICRO-ORGANISMS

EN ISO 374-5	EN ISO 374-5
<b>Protection against bacteria, fungi</b>	<b>Protection against bacteria, fungi, virus</b>

### EN 388 MECHANICAL HAZARDS

PERFORMANCE LEVELS	0-4	0-5	0-4	0-4	A-F (P)
Impact protection					
Cut resistance according to ISO 13997					
Puncture resistance					
Tear resistance					
Blade cut resistance					
Abrasion resistance					

### CHEMICAL RISKS

EN ISO 374-1	EN ISO 374-1	EN ISO 374-1
<b>Type A</b>	<b>Type B</b>	<b>Type C</b>
<b>U V W X Y Z</b>	<b>X Y Z</b>	
<b>A</b> Methanol	<b>J</b> n-Heptane	
<b>B</b> Acetone	<b>K</b> Sodium hydroxide 40%	
<b>C</b> Acetonitrile	<b>L</b> Sulphuric acid 96%	
<b>D</b> Dichloromethane	<b>M</b> Nitric acid 65%	
<b>E</b> Carbon Disulfide	<b>N</b> Acetic acid 99%	
<b>F</b> Toluene	<b>O</b> Ammonia 25%	
<b>G</b> Diethylamine	<b>P</b> Hydrogen peroxide 30%	
<b>H</b> Tetrahydrofurane	<b>S</b> Hydrofluoric acid 40%	
<b>I</b> Ethyl acetate	<b>T</b> Formaldehyde 37%	

### RADIOACTIVE CONTAMINATION

EN 421



### ELECTROSTATIC DISCHARGE PROTECTION

EN 16350



For more details: [www.mapa-pro.com](http://www.mapa-pro.com)

**MAPA**<sup>®</sup>  
PROFESSIONAL

## SPECIFIC ADVANTAGES

- PVC specially designed for use in extreme cold (-10°C) while preserving the flexibility of the glove
- Good resistance to oils, greases and hydrocarbons
- Previous name: Temp-Sea 770

## MAIN FIELDS OF USE

### Fishing and Work at sea

- Handling produce

### Food industry

- Maintenance and work in cold stores

### Transport

- Handling of liquids at low temperatures (water, oil, hydrocarbons, etc.)

### Other industries

## INSTRUCTIONS FOR USE

### Instructions for use

- It is recommended to check that the gloves are suitable for the intended use, because the conditions of use at workplace may differ from the "CE"-type tests.
- Put the gloves on dry, clean hands.
- Do not use the gloves in contact with a chemical for a duration in excess of the measured breakthrough time. Refer to the website [www.mapa-pro.com](http://www.mapa-pro.com) or contact the Technical Customer Service - MAPA PROFESSIONAL ([stc.mapaspontex@mapaspontex.fr](mailto:stc.mapaspontex@mapaspontex.fr)) in order to know this breakthrough time. Use 2 pairs alternatively when in long duration contact with a solvent.
- Turn the cuff end down in order to prevent a hazardous chemical from dripping onto the arm.
- Ensure the inside of the gloves is dry before putting them on again.
- Inspect the gloves for cracks or snags before reusing them.

### Storage conditions

- Store the gloves in their original packaging protected from humidity and heat.

### Laundering conditions

- Before taking off the gloves, clean them as appropriate:
- in use with paints, pigments and inks : wipe with a clean cloth dampened with a suitable solvent, and rub over with a dry cloth
- in use with acids or alkalis : thoroughly rinse the gloves under running water and rub over with a dry cloth
- Caution : improper use of the gloves or submitting them to a cleaning or laundering process which is not specifically recommended can alter their performance levels.

### Drying conditions

- Ensure the inside of the gloves is dry before putting them on again.

### Food contact US

- FDA 21CFR 177.2600

## LEGISLATION

This product is not classified hazardous according to the regulation (EC) n°1272/2008 of the European Parliament and of the Council. This product does not contain more than 0.1 % of substance of very high concern (SVHC) or any substance included in the annex XVII of the regulation n° 1907/2006 of the European Parliament and of the Council (REACH).

- **UE type certificate or CE type examination certificate** : 0075/014/162/01/19/0112
- **Issued by the notified body nr** : 0075 - C.T.C. – 4 rue Hermann Frenkel - F- 69367 LYON Cedex 07
- **Quality assurance certificat** : 0334 Asqual 14 rue des Reculettes -F-75013 PARIS